Contact Chain Resistance Tests

Important Details

- Each chain has 14 series contacts and 7 series resistive pads
- Each chain has diffused segments measuring [L = $150 \ \mu m \ x \ W = 50 \ \mu m$]
- 2C: 14 contacts connecting metal to diffused Si
- 2D: 14 contacts connecting metal to poly-Si



